## DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 10/01/2015 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	` '	X2) MULTIPLE CONSTRUCTION  A. BUILDING <b>02</b>		(X3) DATE SURVEY COMPLETED	
		155490	B. WING _	B. WING		09/29/2015	
NAME OF PROVIDER OR SUPPLIER  AMBASSADOR HEALTHCARE				STREET ADDRESS, CITY, 705 E MAIN ST CENTERVILLE, IN 47			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	(EACH CORF	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		ION
K 000	INITIAL COMMENTS		K	000			
	INITIAL COMMENTS  A Life Safety Code and Environmental Preoccupancy survey for the relocation of the previously unlicensed rooms RH1 and RH2 in the Southeast Hall was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a).  Survey Date: 09/29/15  Facility Number: 000456 Provider Number: 155490 AIM Number: 100288750  At this Life Safety Code and Environmental Preoccupancy survey, Ambassador Healthcare was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 18, New Health Care Occupancies for rooms RH1 and RH2 in the Southeast Hall and 410 IAC 16.2.  This one story Southeast Hall addition was determined to be of Type V (111) construction and fully sprinkled. The facility has a fire alarm system with smoke detection in the corridors, spaces open to the corridors and hard wired smoke detectors in all Southeast Hall resident sleeping rooms. The facility has a capacity of 137 and had a census of 103 at the time of this survey.  All areas where residents have customary access were sprinkled and all areas providing facility services were sprinkled.						

ABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

## DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 10/01/2015 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	1	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>02</b>		(X3) DATE SURVEY COMPLETED	
		155490	B. WING _	<del></del>		09/29/2015	
	ROVIDER OR SUPPLIER		STREET ADDRESS, CITY, STATE, ZIP CODE  705 E MAIN ST  CENTERVILLE, IN 47330				
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	(EACH CORRECTIVE ACTION	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		
K 000	Continued From page Quality Review comp		KO				